

序文の要約 ; Preface ; Contents (A survey of polymer crystallization by X-ray diffraction)

メタデータ	言語: en 出版者: SKP 公開日: 2008-01-31 キーワード (Ja): キーワード (En): 作成者: Asano, Tsutomu, Mina, Md. Forhad メールアドレス: 所属:
URL	<a href="http://hdl.handle.net/10297/558">http://hdl.handle.net/10297/558</a>

# Contents

## Chapter 1 Fundamentals of Crystallography

1.1. Crystal Structure .....	1
1.2. Concept of Lattice Planes.....	2
1.3. Bragg's Condition .....	3
1.4. Reciprocal Lattice .....	3
1.5. The Ewald Sphere Construction .....	5
1.6. Polymer Structure .....	7

## Chapter 2 X-Ray Diffraction Theory

2.1 Basic Theory .....	9
2.1.1 Basics for X-ray diffraction .....	9
2.1.2 Scattering by a single electron .....	9
2.1.3 Scattering by an atom consisting of many electrons.....	10
2.2 Fourier Transformation .....	12
2.2.1 Relation in the Fourier transform.....	12
2.2.2 Examples of the Fourier transform .....	13
2.3 The Convolution Theory .....	17
2.3.1 Convolution function.....	17
2.3.2 Fourier transform of the convolution.....	17
2.3.3 Application of the convolution theory.....	18

## Chapter 3 X-Ray Diffraction Experiments

3.1 Properties of X-ray .....	22
3.2 Generation of X-ray by Tubes .....	22
3.2.1 Continuous X-rays .....	23
3.2.2 Characteristic X-rays.....	23
3.2.3 X-ray tube .....	23
3.2.4 Rotating anode tube.....	24
3.3 Synchrotron Radiation .....	24
3.4 Monochromatization .....	25
3.4.1 Single crystal monochromator.....	25
3.4.2 Filtration .....	25
3.5 X-ray Detection.....	26
3.5.1 Photographic film.....	26
3.5.2 Imaging Plate .....	26
3.5.3 Counters .....	26
3.5.4 Position Sensitive Proportional Counter (PSPC) .....	26
3.5.5 CCD.....	27
3.6 Wide-Angle X-ray Scattering (WAXS) .....	27
3.6.1 Experimental set-up.....	27
3.6.2 Flat film technique (Photographic film or IP).....	27
3.6.3 Cylindrical camera .....	28
3.7 Middle- and Small-Angle X-ray Scattering (MAXS & SAXS).....	29
3.8 <i>In-situ</i> X-ray Measurement.....	29

## Chapter 4 Oriented Crystallization of Poly (ethylene terephthalate)

4.1 Introduction .....	31
4.2 Sample Preparation and Characterization .....	31
4.3 WAXS Measurements .....	32
4.3.1 Initial crystallization of the cold drawn PET .....	32
4.3.2 Analysis of the tilted orientation .....	33
4.4 <i>In situ</i> Observation by MAXS .....	35
4.5 SAXS Measurements .....	36
4.5.1 4-Point SAXS pattern .....	36
4.5.2 Evaluation of thickness and inclination of the lamellae .....	36
4.5.3 Finer analysis of the layer structure .....	37
4.6 Crystallization Process of Cold Drawn PET .....	38
4.6.1 Initial crystallization at low temperatures .....	38
4.6.2 Molecular orientation by cold drawing .....	38
4.6.3 Analysis of the meridional reflection .....	39
4.6.4 Development of lamellar structure .....	39
4.6.5 Tilting mechanism.....	40
4.6.6 Development of triclinic crystals .....	41
4.7 Effect of the Drawing Temperature .....	42
4.8 Simulation by Light Scattering. ....	43
4.8.1 Analysis of smectic structure .....	43
4.8.2 Analysis of the SAXS intensity. ....	44
4.8.3 Analysis of the SAXS streak. ....	45
4.8.4 Analysis of the 4-point pattern. ....	45
4.9 Concluding Remarks .....	46

## Chapter 5 Temperature Slope Crystallization of Polymers

5.1 Introduction. ....	48
5.2. Construction of TSC Instruments .....	49
5.2.1 TSC apparatus for a film specimen by Fujiwara .....	49
5.2.2 Apparatus of TSC devised by Asano .....	50
5.3 Features of the Specimens Prepared by the TSC Method .....	52
5.4 TSC of paraffin and polyethylene .....	56
5.4.1 Observation of the melt-solid boundary .....	56
5.4.2 <i>In-situ</i> X-ray measurements of PE-2000 .....	57
5.4.3 <i>In-situ</i> TSC of C36 .....	60
5.4.4 Dynamic features of TSC .....	61
5.4.4.1 Lamellar and molecular orientation .....	61
5.4.4.2 Movement of the crystallizing plane .....	61
5.4.4.3 Structure in the supercooled region .....	61
5.5 TSC of isotactic polypropylene (iPP) .....	62
5.5.1 Crystalline phases of iPP .....	62
5.5.2 Methodology of TSC for iPP. ....	62
5.5.3 Optical measurements on the melt-solid boundary .....	63
5.5.4 X-ray diffraction measurements .....	64
5.5.5 Process of X-ray measurements .....	65
5.5.6 Mechanism of iPP crystallization .....	68

## Chapter 6 Phase Transition of Hexatriacontane

6.1 Introduction .....	71
6.2 Molecule and Phases of C36 .....	71
6.3 $M_L \rightarrow M_H$ Transition of C36 Single Crystal. ....	72
6.3.1 Thermal measurements by DSC.....	72
6.3.2 Basic investigation of the $M_L \rightarrow M_H$ transition .....	73
6.3.3 DSC and X-ray diffraction studies by the step-wise heating .....	74
6.3.4 Twinned mechanism of the $M_L \rightarrow M_H$ transition .....	76
6.3.5 Stand-up mechanism of the $M_L \rightarrow M_H$ transition.....	78
6.3.6 Simultaneous measurements of DSC and X-ray diffraction.....	79
6.4 Phase Transition Studies of Bulk C36 by TSC .....	80
6.4.1 Experimental conditions .....	80
6.4.2 Appearance of the oriented rotator phase.....	81
6.4.3 Oriented crystalline form of bulk C36.....	82
6.4.4 Mechanism of $R \rightarrow M_H$ transition.....	84
6.5 Onset Mechanism of the Phase Transitions.....	85
6.5.1 Molecular motion during the $M_L \rightarrow M_H$ transition.....	85
6.5.2 Effect of impurity on the transition.....	86
6.6 Concluding Remarks.....	94

## Chapter 7 Deformation of Polymers

7.1 Introduction .....	97
7.2 Cold-rolling of $\beta$ -PP.....	98
7.2.1 Oriented $\beta$ -PP crystallized by TSC.....	98
7.2.2 Method of rolling and conditions of X-ray diffraction.....	100
7.2.3 A-roll deformation.....	101
7.2.4 B-roll deformation.....	104
7.2.5 C-roll deformation.....	108
7.2.6 Anisotropic character of lamellar deformation.....	109
7.2.7 Effect of annealing after deformation.....	110
7.2.8 Transformation from a- to c-axis orientation.....	110
7.3 Contractive Deformation of Drawn PET.....	111
7.3.1 Experimental setup.....	111
7.3.2 Sample drawing .....	112
7.3.3 Contraction of the cold drawn PET.....	112
7.3.4 Contraction of the hot drawn PET.....	113
7.3.5 X-ray diffraction measurements during the contraction.....	113
7.3.6 Relation between contractive deformation and internal structure.....	116

## Chapter 8 Epitaxial Growth in Polymers

8.1 Introduction.....	119
8.2 Preparation and Characterization of Epitaxial Samples.....	120
8.3 X-ray Diffraction Studies.....	121
8.3.1. Structure of the oriented iPP/HDPE film.....	121
8.3.2. <i>In situ</i> SAXS and WAXS measurement. ....	122
8.3.3. Three dimensional analysis. ....	123
8.4. Mechanism of Epitaxial Crystallization of PE onto the c-axis-oriented PP.....	123

## Chapter 9 Microhardness of Polymers

9.1 Introduction.....	126
9.2 Indentation Geometry.....	126
9.3 Comparative Studies of PP by Microhardness and X-ray.....	128
9.4 Comparative Studies of PET by Microhardness and X-ray.....	129

## Chapter 10 Polymer Crystallinity

10.1 Introduction.....	135
10.2 Crystallinity and Crystal Distortion of PET.....	135
10.2.1 Preparation and characterization of PET samples.....	135
10.2.2 WAXS measurements.....	136
10.2.3 Background calculation for the fitting method.....	137
10.2.4 Comparison of $w_c$ and $k$ .....	139
10.2.5 Amount of lattice distortion.....	141
10.3 Theoretical Development of Crystallinity Measurement.....	142
10.3.1 Methods of Ruland and Vonk.....	142
10.3.2 Modified Vonk's method.....	143
10.3.3 Calculation of $b(k, s_p)$ .....	144
10.3.4 Evaluation by the modified Vonk's method.....	147
10.3.5 Examples of the evaluation.....	147
10.3.6 Discussion.....	150

---

A SURVEY OF TEMPERATURE SLOPE CRYSTALLIZATION (TSC) FOR THE  
ORIENTED CRYSTALLIZATION OF POLYMER LAMELLAE

By Yasuna FUJIWARA